


Mechanical Fixing



Remove the transparent Lid and mount the Sensor using the 4 corner fixing holes.

Wiring & Termination

